



Assembly Instructions

1) Strip the cable to the dimensions shown. Take care not to nick the centre conductor or braid.


- A = 7mm
- B = 5mm
- C = 3mm




2) Slide the clamp nut, washer and grommet over the cable. Place the taper clamp over the braid and push back against the cable jacket. Pull the braid back over the taper clamp and trim level with the rear as shown.



3) Solder the contact onto the centre conductor.



4) Insert the cable and parts into the connector body. Tighten the clamp nut using appropriate wrenches.



Connector Part Number	Stripping Tool Part Number	Crimp Tool Part Number	Hex Size	
			Pin	Ferrule
VBS10-2031	N/A	N/A	N/A	N/A
VBS10-2031-1202	N/A	N/A	N/A	N/A
VBS10-2031-1203	N/A	N/A	N/A	N/A
VBS10-2033-1202	N/A	N/A	N/A	N/A
VBS10-2051	N/A	N/A	N/A	N/A
VBS10-2051-1202	N/A	N/A	N/A	N/A
VBS10-2051B	N/A	N/A	N/A	N/A
VBS10-2057-1202	N/A	N/A	N/A	N/A

CAD Issue	PDC	2	26 Apr 02
First Issue	PDC	1	23 Feb 00
DESCRIPTION OF REVISION	APPVD	ISS	DATE

Connectivity Solutions
 7-13 Russel Way,
 Widford Industrial Estate,
 Chelmsford, Essex,
 CM1 3AA, UK.
 Tel: +44 (0) 1245 359515
 Fax: +44 (0) 1245 358938

SCALE: Not To Scale

DIMENSIONS: mm

TOLERANCES:

DRAWN BY: P Couzens

CHECKED BY: P Couzens

APPROVED BY: S Nash

DATE: 26 Apr 02

DESCRIPTION:

Stripping and Assembly
 Instructions for BNC Clamp
 Plugs

DRAWING NUMBER:

VAIB1202

PAGE: 1 OF 1