


# ASSEMBLY INSTRUCTIONS

AmphenolRF

HD - BNC  
CRIMP PLUGS

REV - 1



PLUG BODY ASSEMBLY




MALE CONTACT



OUTER FERRULE


AMPHENOL NUMBER	CABLE	HEX CRIMP DATA			STRIPPING DIMENSIONS, INCHES (MM)		
		CAVITY FOR CONTACT	CAVITY FOR OUTER FERRULE	CTL SERIES TOOL NUMBER	A	B	C
34-1026	1855A, T8550A	0.042 (1.1) □	0.178 (4.6) ◊	CTL-15	0.156 (3.96)	0.233 (5.92)	0.562 (14.27)
34-1037	1855ENH, 0.6/2.8	0.042 (1.1) □	0.197 (5.0) ◊	-	0.156 (3.96)	0.250 (6.35)	0.594 (15.09)
34-1037-100	1855ENH, IMAGE 360, 1.0/4.8	0.042 (1.1) □	0.197 (5.0) ◊	-	0.156 (3.96)	0.250 (6.35)	0.594 (15.09)
34-1033	TFC HD 210	0.042 (1.1) □	0.213 (5.4) ◊	-	0.156 (3.96)	0.233 (5.92)	0.562 (14.27)
34-1027	1695A	0.042 (1.1) □	0.255 (6.5) ◊	CTL-14	0.156 (3.96)	0.235 (5.97)	0.564 (14.33)
34-1025	1505A, T5050A, IMAGE 720, 0.8/3.7	0.042 (1.1) □	0.255 (6.5) ◊	CTL-14	0.156 (3.96)	0.235 (5.97)	0.564 (14.33)
34-1017-300	1694A, T6940A, IMAGE 1000	0.042 (1.1) □	0.278 (7.1) ◊	-	0.156 (3.96)	0.235 (5.97)	0.564 (14.33)

STEP 1




Step 1 - Strip cable jacket, braid, and dielectric to dimensions in table above. All cuts are to be sharp and square. Important : Do not nick braid dielectric and center conductor. Slide outer ferrule onto cable as shown.

STEP 2



Step 2 - Flare slightly end of cable braid to facilitate insertion of inner ferrule. Place contact on cable center conductor so that it butts against cable dielectric. Crimp contact in place using die set cavity indicated in table above.

STEP 3



Step 3 - Install cable assembly into body assembly so that inner ferrule portion slides under braid. Push cable assembly forward until contact snaps into place in insulator. Slide outer ferrule over braid and up against connector body. Crimp outer ferrule using die set cavity specified in table above.

Use tool 227-T2000 (1 ft long) or 227-T2000-2FT (2 ft long ) for installation and removal of the HD-BNC plug.