molex®

ENGINEERING SPECIFICATION

INSTALLATION INSTRUCTION SHEETS

1.0 SCOPE

This specification consists of installation instructions for the Self-Contained Power Connector for tap splice.

2.0 PURPOSE

To define material number system for the above instructions.

3.0 REFERENCE MATERIAL NUMBERS

Part Number: 19402-1000 **Engineering Number: COC-3**

See pages 2-3 for the actual instruction sheets. These pages can be used as originals.

4.0 DEFINITIONS

Not applicable.

5.0 PROCEDURES

Place one (1) instruction sheet in the smallest unit container.

6.0 IMPLEMENTATION

December 6, 2005

REVISION:	ECR/ECN INFORMATION:	TITLE: SELF CONTAINED POWER CONNECTOR (COC-3)			SHEET No.
D1	EC No: 123456	INSTA	4 - (0		
D1	DATE: 2019/ 09 / 23		1 of 3		
DOCUMENT NUMBER:		CREATED / REVISED BY:	CHECKED BY:	APPROVED BY:	
SD-19402-004		ETHRODAHL/ DMYRICK	JMACNEIL	JMACNEIL	

TEMPLATE FILENAME: ENGINEERING_SPEC[SIZE_A](V.1).DOC

COC-3 Self Contained Power Connector Installation Instructions For Tap Splice

The 2-circuit-with-ground tap connector is used to tap non-metallic-sheathed cable in the following wire

ranges and types:

٧	Vire			Optional	
R	ange			Bench	Optional
1	AWG	Description	Order No.	Arbor Press	Hand Tool
1	2-14	Self Contained Power Tap Connector - 2 circuit w/ ground for solid wire	19402-1000 (COC-3)	64006-0200	19285-0074





Reference Information

UL File Number: E182087 CSA File Number: LR18689-C53 NEC Article: 550, 551, and 545

HUD Section: 3280.801

Current: 20A Voltage: 300V

Recommended Cable Stripper



Klein Model: 11061 or K1412CAN or Southwire: SNM1214

Installation Procedure:

- 1. Carefully strip sheath and paper coverings and prepare the wires to the configuration as shown in **Figure 1**. For reference in the absence of a measuring tool, the distance shown in **Figure 1.1** is approximately equal to strip length.
- 2. Hold the clear strain relief cover with bottom facing upward as shown in Figure 2.
- 3. Lay wire into locator slots, making sure the black wire is placed into locator slots marked BLK shown in **Figure 2**. Use the two wire locators and spreaders to help guide the wire into place. Press the cable sheath into the integral strain relief slot.
- **4.** While holding the strain relief cover, position the housing's hinge posts into the hinge slots and press down until both lock into place as shown in **Figure 2**.
- 5. Close the strain relief cover and housing by hand. Place the connector assembly into Molex tool as shown in **Figure 3**. Squeeze the tool until the connector bottoms out and the locking latches engage on both sides. OR alternately, squeeze the top and bottom closed with tongue and groove pliers as shown in **Figure 3.1**. Pliers must be a minimum of 10" long. Squeeze firmly on both sides, squarely across the connector with the bottom jaw of the pliers butted up against the T-extension in the housing to ensure wires seat completely into slots.
- 6. Inspect the connector to ensure the wires have been properly engaged into the housing assembly contacts. A properly terminated wire is fully seated into its proper slots with no significant bow of the cover. If the wires are not properly seated into the housing assembly contacts, the wires must be re-terminated with a NEW CONNECTOR. Once the cover has been closed the connector cannot be re-used. Failure to comply with this procedure may result in the failure of the connector.











