## HLF4 - SERIES ASSEMBLY INSTRUCTIONS FOR **HLF4 - HME LEVELLING FEET** PLINTH CORNER


## **INSTRUCTIONS (USING PLINTH):**

A) Raise enclosure with installed plinth corner blocks minimum 4" off the ground.

B) Install levelling (item 1) feet into plinth corner blocks.

C) Lower enclosure onto feet and adjust to desired height.

ITEM	DESCRIPTION	QTY
1	Levelling Foot - 1/2-13	4
2	Nut - 1/2-13	4
TOOL BOX	3/4" Socket 14MM Open End 3/ Wrench Wrench	4 Open End Wrench



## **INSTRUCTIONS (WITHOUT PLINTH):**

A) Raise enclosure off the ground minimum 4"

B) Remove bolts and washers one at a time from bottom of enclosure. Make sure to keep the washers.

C) Install provided nut (item 2) onto levelling foot (item 1) along with washers, leave some threads open on the levelling foot (item 1) to thread into frame.

D) Install levelling foot (item 1) into frame, repeat for all four corners.

E) Lower enclosure back onto the ground and adjust feet to make it level.

F) Tighten the installed nut (item 2) to the bottom panel to hold bottom panel on.

