

PLUG KIT, RJ POINT FIVE

1. PURPOSE 目的

Define the packaging specification and packaging method of PLUG KIT, RJ POINT FIVE.

订定 PLUG KIT, RJ POINT FIVE 产品之包装规格及包装方式。

2. APPLICABLE PRODUCT 适用范围

Product Part No.	Description
2007312-1/2	PLUG KIT, RJ POINT FIVE
2007412-2	RJ POINT FIVE, PLUG CONTACT, MODULE ASSEMBLY
2007697-5	RJ POINT FIVE, PLUG SHIELD
2007590-2	RJ POINT FIVE, STRAIN RELIEF SUBASSEMBLY
2007588-3	TETHER, PLUG, RJ POINT FIVE
2007501-2	WIRE HOLDER, PLUG, RJ POINT FIVE
2132999-1/2	PLUG KIT, RJ POINT FIVE

3. PACKAGING MATERIAL AND USAGE 包装材料

Package	Part No.	Description	Size(mm)	2007312-1 2132999-1	2007312-2 2132999-2	2007412-2 2007697-5	2007590-2	2007588-3	2007501-2
INNER	623872-2	PE BAG, SELF-SEALING	108x162	1/1	-	-	-	1/300	-
	1533282-3	PE BAG	229x318	-	5/1	1/300	1/300	-	1/600
	623865-6	INNER LABEL	38x25	-	5/1	-	-	-	-
	623865-4	INNER LABEL	38x25	1/1	-	1/300	1/300	1/300	1/600
MIDDLE	-	-	-	-	-	-	-	-	-
OUTER	110455-2	BUBBLE PACK	349x304x12	1/200	1/1	1/2100	1/1200	1/6000	1/15000
	12110	SHIPPING BOX	349x147x146	1/200	1/1	1/2100	1/1200	1/6000	1/15000
	623865-5	OUTER LABEL	102x102	1/200	1/1	1/2100	1/1200	1/6000	1/15000

	Inner	Middle	Outer
LABEL	623865-6 or 623865-4	-	623865-5
SEALING	Tape	-	Tape

DR
Sam Wu

CHK
Sean Xu

APVD
Ansin Yang

4. PACKAGING QUANTITY 包装数量

P/N	Inner	Middle	Outer
2007312-1 2132999-1	1 kit/bag	-	200 kits/box
2007312-2 2132999-2	-	-	1 kit/box
2007412-2	300 pcs/bag	-	2100 pcs/box
2007697-5	300 pcs/bag	-	2100 pcs/box
2007590-2	300 pcs/bag	-	1200 pcs/box
2007588-3	300 pcs/bag	-	6000 pcs/box
2007501-2	600 pcs/bag	-	15000 pcs/box

5. PACKAGING METHOD 包装方法
For 2007312-1/2; 2132999-1/2:

5.1.1. **Only for 2007312-1 & 2132999-1:** Place parts of product into small polybag and self-seal it.

按图纸要求数量，将各个部件如表1所示一起放入一个小塑料袋中并自封其袋口。

Part Number	Component Part Number	Quantity	Bag part number	Sealing
2007312-1	2007412-1	1 pc	623872-2	self-seal
	2007697-4	1 pc		
	2007590-1	1 pc		
	2007588-1	1 pc		
	2007501-1	2 pcs		

表1

5.1.2. **Only for 2007312-2 & 2132999-2:** Place parts of product into small polybag and heat-seal it.

按图纸要求数量，将每种部件如表2所示各用一个小塑料袋包装好并自封其袋口。

Part Number	Component Part Number	Quantity	Bag part number	Sealing
2007312-2	2007412-1	300 pcs	1533282-3	heat-seal
	2007697-4	300 pcs	1533282-3	
	2007590-1	300 pcs	1533282-3	
	2007588-1	300 pcs	1533282-3	
	2007501-1	600 pcs	1533282-3	

表2

5.2. Place an inner label on the side of ploybag.

在塑料袋上贴一内标签(标签样板: 见 Label-WI.)。

5. PACKING METHOD 包装方法

5.3. Set up a box & secure bottom flaps with tape.

折叠好一个包装箱，并用胶带封好箱底。

5.4. Place half piece of folio bubble pack with bubble facing down.

在箱底放入半块气泡垫，气泡面朝下。

5.5.1. **Only for 2007312-1 & 2132999-1:** Place 200 bags with parts into the box.

将200袋产品整齐放入箱中。

5.5.2. **Only for 2007312-2 & 2132999-2:** Place 5 bags with parts into the box.

将5袋部件整齐放入箱中。

5.6. Place half piece of folio bubble pack on the top of the parts, and bubble facing up.

将半块气泡垫放在产品的上面，气泡面朝上。

5.7. Seal the box with tape. And place product identification label in "product id" marked on box.

用胶带封箱，在箱外印有“PRODUCT ID”标识处贴上外标签。

For 2007412-2; 2007697-5; 2007590-2; 2007588-3; 2007501-2:

5.1. Place an inner label on the middle of polybag.

在一个塑料袋的中间位置贴上内标签。

5.2. Weigh or count products qty as 3 put into a bag & heat seal it.

按3中规定数量称重或数数后装入一塑料袋中并热封其开口。

5.3. Set up a box & secure bottom flaps with tape.

折叠好一个包装箱，并用胶带封好箱底。

5.4. Place half piece of folio bubble pack with bubble facing down.

在箱底放入半块气泡垫，气泡面朝下。

5.5. Place bags have packaged into box, label side facing up.

将数袋已包装好的产品放入箱中，有标签的一面朝上。

5.6. Place half piece of folio bubble pack on the top of the parts, and bubble facing up.

将半块气泡垫放在产品的上面，气泡面朝上。

5.7. Seal the box with tape. And place product identification label in "product id" marked on box.

用胶带封箱，在箱外印有“PRODUCT ID”标识处贴上外标签。