



TOLERANCES, TOOLING AND ITS REQUIREMENTS.


10. CUT LENGTH IS ASSEMBLY LENGTH MINUS OVERALL LENGTH SUBTRACTOR.

F:\DWG\MISC\MKTG\PFSS-XX-XX-XX-XX-XX-XXX-MKT.SI DDRW

BY: E WRIGHT 02/16/2010 | SHEET 1 OF 2







DESCRIPTION:

DO NOT SCALE DRAWING

SHEET SCALE: 2:1

PESS CABLE ASSEMBLY

PESS-XX-XX-X-XX.XX-XX-XXX
BY: E WRIGHT 02/16/2010 SHEET 2 OF 2

F:\DWG\MISC\MKTG\PESS-XX-XX-XX-XXX-XXX-MKT.SLDDRW