

UPM R/A KEYED GUIDE PIN
1. PURPOSE 目的

Define the packaging specification and packaging method of UPM R/A KEYED GUIDE PIN.

订定 UPM R/A KEYED GUIDE PIN 产品之包装规格及包装方式。

2. APPLICABLE PRODUCT 适用范围

Product Part No.	Description
0/1/2-1469265-1~9	UPM R/A KEYED GUIDE PIN

3. PACKAGING MATERIAL 包装材料

Package	Part No.	Description		Usage
INNER	-	TRAY	From vendor	1/20
MIDDLE	-	-		
OUTER	12110	SHIPPING BOX	349x148x146	1/240
	623853-1	Poly Tape		5.0Meter/240
	110455-2	Bubble Wrap	-	1/240
	623865-1	OUTER LABEL	-	1/240

	Inner	Middle	Outer
LABEL	-	-	623865-1
SEALING	-	-	Tape

4. PACKAGING QUANTITY 包装数量

Product No.	Inner	Middle	Outer
0/1/2-1469265-1~9	20 pcs/tray	-	240 pcs/box

 DR
Sam Wu

 CHK
Mickey Wen

 APVD
Ansin Yang

5. PACKING METHOD 包装方法

5.1. Keep supplier inner pack for the products to prepare for shipping packing.

保留供应商的内包装以准备外箱包装。

5.2. Set up shipping box and secure bottom flaps with tape.

折叠好一纸箱，并用胶带封住箱的底部。

5.3. Place one half of Air Cap(110455-2) in the bottom shipping box, Bubble Face down.

将一块气泡垫沿宽度方向剪切分离，放置其中一半于箱底，气泡朝下。

5.4. Wrap 13 trays(one empty tray on top) with poly tape as Figure 1 and then place it on the air cap in shipping box.

将13个tray(一个空Tray)的产品(240 pcs)用胶带沿长度方向两缠绕约3圈(Figure 1)，然后置于外箱内气泡垫上。




Figure 1

5.5. Place another half of air cap(110455-2) on top of tray packing , bubble up

将另外一半气泡垫置于最上面，气泡朝外。

5.6. Seal the box with tape. And place product identification label in appointment area on the shipping box.

用胶带封箱，在箱外的指定位置贴上外标签。